













IRS-101-1A ON-OFF  
SPST 3P  
RS-102-1A ON-ON  
SPDT 3P






IRS-101-1B ON-OFF  
SPST 3P  
RS-102-1B ON-ON  
SPDT 3P






IRS-101-1C ON-OFF  
SPST 3P  
RS-102-1C ON-ON  
SPDT 3P







IRS-201-1A ON-OFF  
RS-201-1A ON-OFF  
SPDT 4P




IRS-201-1B ON-OFF  
RS-201-1B ON-OFF  
SPDT 4P



IRS-201-1C ON-OFF  
RS-201-1C ON-OFF  
SPDT 4P



Cap options




A

B

C

Cap marking



C1

C2

C3

C4

C5

C6

C7

C8

C9

C0

